



ಕರ್ನಾಟಕ ಸರ್ಕಾರ
Public Works Department

Building Condition / Fitness Certificate

(a) Name of the Building : Shree Jagajyothi Basaveshwara Vidyavardhaka Sangha
(b) Address : Pulakeshi Nagar Vijayapur-586109

Details of Building

(a) Site Area (in Sqm) : 2446
(b) Built-up Area (in Sqm) : 2446
(c) No. of Floors of the Building : 3

S. No.	Floor/ಮಹಡಿ	Area (in sqm)/ಪ್ರದೇಶ (ಚದರ ಮೀ)	Remarks/ಲಿಪಿಬರಹ
1.	1	610	Building is safe as per norms of NBC 2016 and its fit to run the school/college.
2.	2	918	
3.	3	918	

(d) Architects/ Structural Designers : ER Nagaraj Babanagar

4. *Donada*
Executive Engineer
P.W.D. Division,
Vijayapur.

As per the above details furnished by Building Owners, the building was inspected. Based on the visual observations the following certificate is issued.

This is to Certify that the building named: Shree Jagajyothi Basaveshwara Vidyavardhaka Sangha owned by Shree Jagajyothi Basaveshwara Vidyavardhaka Sangha is Structurally Safe for College Purpose.